MAD 000001

30.20

STATE OF ILLINOIS

DEPARTMENT OF NUCLEAR SAFETY

1035 OUTER PARK DRIVE • SPRINGFIELD, ILLINOIS 62704
217-785-9900 • 217-782-6133 (TDD)

George H. Ryan
Governor

Thomas W. Ortciger
Director

October 6, 2000

Department of the Army
St. Louis District, Corps of Engineers
8945 Latty Avenue
Berkeley, Missouri 63134

Attn: Sharon R. Cotner, FUSRAP Program Manager

Re: Review Draft - "Post-Remedial Action Report for the Madison FUSRAP Site"

Dear Ms Cotner:

The Illinois Department of Nuclear Safety (Department) has no specific comments regarding the draft report referenced above.

Representatives of the Department visited the site during and after remediation activities, and conducted random verification survey measurements and sampling. Results of alpha and beta/gamma direct measurements, as well as laboratory analyses of collected samples, suggest that residual post-remediation contamination is below the decontamination limit guidelines specified in 32 Illinois Administrative Code. Note that this determination is based on the Department's representative survey, which is intended to evaluate the required comprehensive survey conducted by remediation contractors. Based on interviews, observations and survey results, it appears that the cleanup objectives were met for all areas of the site that were addressed by the remedial action.

Should you have any questions, please contact me at (217) 785-9947.

Sincerely,

Gary W. McCandless, P.E., Manager
LLRW Licensing & Site Decommissioning Section
Division of Radioactive Materials

cc: Lou DeArco

recyclable

GWM:DSP